

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re GO Ms. 20/70/PWD Dt. 23-01-1970)

- 1 Name of the Officer Jose. H. Jones
- 2 Name of the School The School of Good Shepherd.
- 3 Location with name of Education District/ Sub. District T.Y.P.M Corporation, North Division
- 4 Classification of Building as specified in column 4 of the application for fitness certificate and size. Six storied R.C.C School Building

Third floor - 1819.26 m²

Fourth floor - 947.70 m²

Grp - Basement floor - 198.66 m²

Ground floor - 1342.12 m²

First floor - 1874.62 m²

Second floor - 1824.42 m²
- 5 Period for which the certificate is issued 2025-2026 Academic year.
- 6 Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)

}

Nil.
- 7 Any major defects noticed which will render the building unsafe in any manner No.
- 8 Whether maintenance works have been done properly Yes.
- 9 Whether the structure is sound or not for conducting classes Yes. Safe for classes under normal weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 15/07/2025 and found to be fit / ~~unfit~~ to conduct classes, for the period 2025-2026 Academic year, for the reasons stated above.

Place: Ullor
Date: 15/07/2025



JOSE.H. JONES
 Assistant Executive Engineer
 IN CHARGE
 T.Y.P.M Corporation
 NO: 605073